

Friday, April 28

Training Sessions

<u>Time</u>	<u>Topic</u>	<u>Location</u>
8:00 AM – 5:00 PM	Criticality	Anasazi South
8:00 AM – Noon	Tritium Dispersion/ Consequence Analysis	Sunset
1:00 PM – 5:00 PM	RadCalc for Windows	DeVargas
1:00 PM – 5:00 PM	Technical Safety Requirements Overview	Sunset

Subgroup Meeting

<u>Time</u>	<u>Topic</u>	<u>Location</u>
6:30 PM – 9:00 PM	Technical Safety Requirements	

Refreshment breaks: 10:00 AM-10:30 AM and 3:00 PM -3:30 PM

Lunch on your own: approximately Noon - 1:00 PM

Saturday, April 29

Training Sessions

<u>Time</u>	<u>Topic</u>	<u>Location</u>
8:00 AM – 5:00 PM	USQ (Day 1 of 2-1/2 days)	Anasazi South
8:00 AM – 5:00 PM	MACCS2	DeVargas
8:00 AM – 5:00 PM	RSAC-6	Pinon
8:15 AM – 9:45 AM	In-Facility Transport & Source Term Modeling	Sunset
10:00 AM - Noon	Fire Source Term Modeling	Sunset
1:00 PM – 5:00 PM	GENNII Computer Code	Chaparral

Tour

<u>Time</u>	<u>Topic</u>	<u>Location</u>
All day *	Field Labs at Energetic Materials Research & Testing Center	Socorro, NM

* Verify exact departure time and assembly point at the registration desk.

Refreshment breaks: 10:00 AM-10:30 AM and 3:00 PM -3:30 PM

Lunch on your own: approximately Noon - 1:00 PM

Sunday, April 30

Training Sessions

<u>Time</u>	<u>Topic</u>	<u>Location</u>
8:00 AM – 5:00 PM	USQ (Day 2 of 2-1/2 day course)	Anasazi South
8:00 AM - 5:00 PM	Introduction to Plutonium Metallurgy	Anasazi North
8:00 AM - Noon	Radiological Dispersion/ Consequence Analysis	Sunset
1:00 PM - 5:00 PM	Chemical Dispersion & Consequence Assessment	Sunset
1:00 PM - 5:00 PM	System Safety Analysis Handbook GENII Computer Code	Chaparral

Subgroup Meetings

<u>Time</u>	<u>Topic</u>	<u>Location</u>
9:00 AM - Noon	Chemical Safety	Zia A
1:00 PM - 5:00 PM	Training	Zia A
6:30 PM - 9:00 PM	Accident Analysis	Sunset

Refreshment breaks: 10:00 AM-10:30 AM and 3:00 PM -3:30 PM

Lunch on your own: approximately Noon - 1:00 PM

Monday, May 1

Training Sessions

<u>Time</u>	<u>Topic</u>	<u>Location</u>
8:00 AM - Noon	USQ Exam (Final Day)	Anasazi South
8:00 AM - 5:00 PM	MACCS2	DeVargas
8:00 AM - 5:00 PM	RSAC-6 Computer Code	Pinon Room
8:00 AM - 5:00 PM	Overview of Hazard Analysis & the SAR	Sunset
1:00 PM - 5:00 PM	ISM and Authorization Agreements	Anasazi South
1:00 PM - 5:00 PM	Safety Analyses in Dealing with Energetic Materials	Anasazi North

Subgroup Meetings

<u>Time</u>	<u>Topic</u>	<u>Location</u>
2:00 PM - 6:00 PM	Authorization Basis	Zia B & C
2:00 PM - 6:00 PM	USQ	Zia A

Evening Social

<u>Time</u>	<u>Topic</u>	<u>Location</u>
7:00 PM - 9:00 PM	Reception	Anasazi

Continental Breakfast 7:00 AM - 8:00 AM

Refreshment breaks: 10:00 AM-10:30 AM and 3:00 PM -3:30 PM

Lunch on your own: approximately Noon - 1:00 PM

Tuesday, May 2

Morning

<u>Time</u>	<u>Topic</u>	<u>Location</u>
8:00 AM – 10 AM	Plenary Session <ul style="list-style-type: none"> • Welcoming • Opening speaker – Emil Morrow for Robert DeGrasse 	Anasazi
10:30 AM - Noon	Breaking News <ul style="list-style-type: none"> • Y-12 Incident – Susan Derrington • Software QA – Charles Martin 	DeVargas
10:30 AM – Noon	Poster Session	Pavilion
10:30 AM – Noon	Facility Disposition Subgroup Meeting	Chaparrel

Afternoon

<u>Time</u>	<u>Topic</u>	<u>Location</u>
Noon – 1:30 PM	SA-2000 Luncheon <ul style="list-style-type: none"> • Luncheon speaker – Ines Triay 	Anasazi
2:00 PM – 5:00 PM	Paper Session 1 – Facility Transition	DeVargas
2:00 PM – 5:00 PM	Paper Session 2 – Integrated Safety Management	Zia A & B
2:00 PM – 5:00 PM	Paper Session 3 – Authorization Basis	Sunset

Evening

<u>Time</u>	<u>Topic</u>	<u>Location</u>
6:15 PM – 10:15 PM *	Dinner Train Ride	Departs from Santa Fe Railroad Station

* See map in your packet.

Continental Breakfast 7:00 AM - 8:00 AM

Refreshment breaks: 10:00 AM-10:30 AM and 3:00 PM -3:30 PM

Wednesday, May 3

Morning

<u>Time</u>	<u>Topic</u>	<u>Location</u>
8:00 AM – 10:00 AM	Plenary Session – <ul style="list-style-type: none"> • <i>A Look at the Japanese Criticality Accident – Consequences & Lessons Learned. T. McLaughlin</i> • <i>Status of Orders, Rules, and IGsR. Black & R. Englehart</i> 	Anasazi
10:30 AM – 12:30 PM	Paper Session 4 – Regulatory Issues	Anasazi North
10:30 AM – 12:30 PM	Paper Session 5 – Nuclear Facility Safety Analysis I	Anasazi South
10:30 AM – 12:30 PM	Paper Session 6 – Non-Nuclear Facility Safety Analysis I	Sunset

Afternoon

<u>Time</u>	<u>Topic</u>	<u>Location</u>
2:00 PM – 3:30 PM	Paper Session 7 - Project Management	Anasazi North
2:00 PM – 3:30 PM	Paper Session 8 – Accident Analysis	Zia A & B
2:00 PM – 3:30 PM	Paper Session 9 – Nuclear Facility Safety Analysis II	Anasazi South
2:00 PM – 3:30 PM	Paper Session 10 – Non-Nuclear Facility Safety Analysis II	Sunset
4:00 PM – 5:30 PM	Paper Session 8 – Accident Analysis (concluded)	Zia A & B
4:00 PM – 5:30 PM	Paper Session 11 - Training	Anasazi North
4:00 PM – 7:00 PM	Chemical Safety Subgroup Meeting	Anasazi South
4:00 PM – 7:00 PM	D&D Panel Discussion	Sunset

Continental Breakfast 7:00 AM - 8:00 AM

Refreshment breaks: 10:00 AM-10:30 AM and 3:30 PM-4:00 PM

Lunch on your own: approximately 12:30 - 2:00 PM

Thursday, May 4

Morning

<u>Time</u>	<u>Topic</u>	<u>Location</u>
8:00 AM – 11:30 AM	Plenary Session <ul style="list-style-type: none">• <i>Outstanding Paper Awards</i>• <i>Closing Speaker B. Cook</i>• <i>Y-12 Accident ... S. Derrington</i>• <i>Overview of Workshop</i>	Anasazi

Afternoon

<u>Topic</u>	<u>Location</u>
Tour of LANSCE	LANL
Tour of DAHRT	LANL
Tour of LANL Waste Facilities	LANL

Continental Breakfast 7:00 AM - 8:00 AM

